

ENGINEERING CHANGE NOTICE **DART AEROSPACE LTD**

Date: 09.06.16	Job No.: 00263	ADR Yes/No: N	ADR Date:	ECN #: 09- 615P
Product No.: D119-646		Created By: RF	Approved By: <i>MP</i>	
Product Name: A119 Skidtube Installation		Checked By: <i>1/</i>	General Manager Approval:	

Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL/JLM	<i>LL/JLM</i>
Production Engineering Coord	Y	EC/DD	<i>EC/DD</i>
Production Document Control	N		
Customer Technical Support	N		

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord	N		
QC Coordinator	N		
Marketing	N		
Customer Order Processing	N		

Reason for Change:	New Issue
--------------------	-----------

Documents Affected: Revised Preliminary Issues of the following: D3848 rev. B dated 09.06.16 D3849 rev. B dated 09.06.16
--

PARTS MUST COMPLY ☒ PREVIOUS PARTS SATISFACTORY ☐

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Product Compatability Matrix	N			
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	N			
9	Update Blue/Pink/DSI Folder and Electronic Files	N			
10	Update Controlled PDF Files	N			
11	Update Master Document List (MDL)	N			
12	Update Document Record (DR)	N			
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	N			
16	Update / Verify ARC Database	N			
17	Create / Update Change Record Form	N			
18	Create / Update PPP's	N			
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	N			
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	N			
22					
23					

Description / Action: D3848-1 Gasket has change D3848-3/-5 no change dated 09.06.16 & D3849 Wearplate dated 09.06.16, these drawings replace previous dated release. D3848-1 dxf file has change, D3848-3/-5 no change; D3849-1/-3/-5 dxf file has change. D3849-3/-5 plate used in D3849-043/-045 doesn't need to rework, because the section changed is cover by the weld. <i>- Make Qty(2) D3849-041 FWD WEARPLATE</i> <i>WRONG DXF'S USED-</i>
--

ECN Verified & Complete: *MP* Date: *09/06/19*